Montana Board of Oil and Gas Conservation Environmental Assessment

Operator: Marathon Oil Company. Well Name/Number: Clark USA 31-14H
Location: SW SE Section 11 T31N R58E
County: Sheridan, MT; Field (or Wildcat) Wildcat
Air Quality
(possible concerns)
Long drilling time: No, 25-35 days drilling time.
Unusually deep drilling (high horsepower rig): <u>Triple derrick drilling rig, to drill to</u>
19,943'MD/9,641'TVD single lateral Bakken Formation test well
Possible H2S gas production: Yes, slight chance of H2S gas.
In/near Class I air quality area: No Class I air quality area.
Air quality permit for flaring/venting (if productive): Yes, DEQ air quality permit required under
<u>75-2-211.</u>
Mitigation:
_X Air quality permit (AQB review)
Gas plants/pipelines available for sour gas
Special equipment/procedures requirements
_ Other:
Comments: <u>Drill a 19,943'MD/9,641'TVD single lateral Bakken Formation test well.</u>
If no gas gathering system exists nearby sweet gas and/or H2S gas can be flared under Board
Rule 36.22.1220. No concerns.
Water Quality
(possible concerns)
Salt/oil based mud: Yes to intermediate casing string hole will be drilled with oil based invert
<u>drilling fluids</u> . Horizontal lateral will be drilled with brine water. Surface casing hole will be
<u>drilled with freshwater and freshwater mud system.</u>
High water table: No high water table anticipated.
Surface drainage leads to live water: Yes, closest drainage is an unnamed ephemeral drainage,
about 1/2 of a mile to the northeast, that drainages to a closed basin, about 7/8 of a mile to the
northwest from this location.
Water well contamination: None, closest water wells are all 1 mile and further from this
location in any direction. Surface hole will be drilled with freshwater to 1850'. Surface casing
will be run and cemented to surface.
Porous/permeable soils: No, silty sandy clay soils.
Class I stream drainage: No, Class I stream drainages.
Mitigation:
X Lined reserve pit
\underline{X} Adequate surface casing
Berms/dykes, re-routed drainage
Closed mud system
Off-site disposal of solids/liquids (in approved facility)
<u>X</u> Other: <u>Semi closed loop mud system to be used</u> . Oil based invert drilling fluids will

be recycled. Cuttings will be mixed with fly ash and buried in the lined cuttings pit.

Comments: 1850' of surface casing will be necessary to cover the base of the Fox Hills aquifer.

Soils/Vegetation/Land Use

(possible concerns)	
Steam crossings: None	anticipated.
High erosion potential:	No, location req
1 1 2 1	-

High erosion potential: No, location requires a moderate cut, up to 16.0' and a moderate fill, up to 14.2', .required.

Loss of soil productivity: <u>Slight.</u>

Unusually large wellsite: No, a large well site 400'X500' for two (2) drilling locations: Clark USA 31-14H and Wegner 34-11H.

Damage to improvements: <u>No, location to be restored after drilling, if nonproductive</u>. <u>If</u> productive unused portion of the drilling pad will be reclaimed.

Conflict with existing land use/values: <u>Slight, surface use is cultivated land.</u>

]	Mitigation
_	Avoid improvements (topographic tolerance)
_	Exception location requested
_	X Stockpile topsoil
_	Stream Crossing Permit (other agency review)
_	X Reclaim unused part of wellsite if productive
_	Special construction methods to enhance reclamation
	Other

Comments: Access will be over existing county gravel road, View Hill Road and existing section line trail. An access trail off the existing county road into this location will be built and/or upgraded. Estimated new road length is about 0.1 miles into the location. Cuttings will be mixed with fly ash and dumped in the lined cuttings pit. Cuttings pit will be backfilled when drilling is completed. Drilling fluids will be recycled or hauled to a Class II disposal. Completion fluids in the reserve pit will be hauled to a commercial Class II disposal.

Health Hazards/Noise

(possible concerns)

Proximity to public facilities/residences: Yes, residences about 5/8 to 3/4 of a mile northwest, 1/2 of a mile to the south, 7/8 of a mile to the west and 5/8 of a mile to the southeast from this location. The town of Medicine Lake, Montana lies about 17.5 miles to the northwest from this location.

Possibility of H2S: _Slight chance of H2S.

Size of rig/length of drilling time: <u>Triple drilling rig 25 to 35 days drilling time</u>.

Mitigation:
_X Proper BOP equipment
Topographic sound barriers
H2S contingency and/or evacuation plan
Special equipment/procedures requirements
Other:

Comments: <u>Adequate surface casing cemented to surface with working BOP stack should mitigate any problems.</u>

Wildlife/recreation		
(possible concerns)		
Proximity to sensitive wildlife areas (DFWP identified): Medicine Lake National Wildlife		
Refuge is about 9 miles to the west from this location.		
Proximity to recreation sites: Medicine Lake National Wildlife Refuge is about 9 miles to the		
west from this location.		
Creation of new access to wildlife habitat: No		
Conflict with game range/refuge management: No		
Threatened or endangered Species: Threatened or endangered species listed on the Region 6		
USFW website are the Piping Plover and Whooping Crane. Candidate species is the Sprague's		
Pipit. NH Tracker website lists nine (9) species of concern as follows: Baird's Sparrow,		
Nelson's Sparrow, Sprague's Pipit, Burrowing Owl, Ferruginous Hawk, Bobolink, Whooping		
Crane, Long-billed Curlew and the Western Hog-nosed Snake. NH Tracker website lists two (2)		
species of concern: Chimney Swift and the Tennessee Warbler.		
Mitigation:		
Avoidance (topographic tolerance/exception)		
Other agency review (DFWP, federal agencies, DSL)		
Screening/fencing of pits, drillsite		
Other:		
Comments: Private cultivated surface land. There may be species of concern that maybe		
impacted by this wellsite. We ask the operator to consult with the surface owner as to what he		
would like done, if a species of concern is discovered at this location. The Board of Oil & Gas		
has no jurisdiction over private surface lands.		
Historical/Cultural/Paleontological		
(possible concerns)		
Proximity to known sites: None identified		
Mitigation		
avoidance (topographic tolerance, location exception)		
other agency review (SHPO, DSL, federal agencies)		
Other:		
Comments: <u>Private cultivated surface land</u> . There may be possible		
historical/cultural/paleontological sites that maybe impacted by this wellsite. We ask the		
operator to consult with the surface owner as to his desires to preserve these sites or not, if they		
are found during construction of the wellsite. The Board of Oil & Gas has no jurisdiction over		
<u>private surface lands.</u>		
Social/Economic (possible concerns)		
Substantial effect on tax base		
Create demand for new governmental services		
Population increase or relocation		
Comments: No concerns		

Remarks or Special Concerns for this site

This will be an 18,8791'MD/9,641'TVD single lateral Bakken Formation test well.
Summary: Evaluation of Impacts and Cumulative effects
No long term impacts expected from the drilling of this well. Some short term impacts will occur, but will be mitigated in time.
I conclude that the approval of the subject Notice of Intent to Drill (does/ <u>does not</u>) constitute a major action of state government significantly affecting the quality of the human environment, and (does/ <u>does not</u>) require the preparation of an environmental impact statement.
Prepared by (BOGC): /s/Steven Sasaki (title:) Chief Field Inspector Date: April 20, 2012 Other Persons Contacted:
Montana Bureau of Mines and Geology, GWIC website (Name and Agency) Water wells in Sheridan County (subject discussed) April 20, 2012 (date)
US Fish and Wildlife, Region 6 website (Name and Agency) ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES MONTANA COUNTIES, Sheridan County, Montana (subject discussed) April 20, 2012
Montana Natural Heritage Program Website (Name and Agency) Heritage State Rank= S1, S2, S3, Location T31N R58E (subject discussed)
<u>April 20, 2012</u> (date)
If location was inspected before permit approval: Inspection date: _August 16, 2011 Inspector: _Schmidt Others present during inspection: _None